

GOVT. OF ASSAM
OFFICE OF THE EXECUTIVE ENGINEER (PWD) SILCHAR BUILDING DIVISION
SILCHAR

No. Bldg/T/Misc/99/2000/221/Pt-I/

Dt.....

To

The Addl Deputy Commissioner cum CEO,
DDMA, Cachar, Silchar.

Sub :- Verification report of the School Building (Assam type) at Bhangarpar "Spring Dales Academy Bhangarpar, Cachar, Assam".

Ref :- Your letter No. DDMA.03/CHR2020/09 dt.02.03.2020.

Sir,

With reference to the above, I have the honour to inform you that, as per visual verification report submitted by the Asstt. Executive Engineer, PWD, Silchar Building Sub-Division-I, Silchar, the above school building appears to be structurally fit for the purpose under normal condition. However, the said report will not be valid against any natural calamities / untoward accident like earthquake, storm, fire etc.

This is for favour of your kind information.

Yours faithfully

Executive Engineer P.W.D.
Silchar Building Division,
Silchar

Memo No. Bldg/T/Misc/99/2000/221/Pt-I/ 192-93

Dt. 14-05-2020

- Copy to :-
- 1) Ms. Amita Sharma Choudhury, Principal Spring Dales Academy Bhangarpar, Cachar, Assam for favour of information.
 - 2) The Asstt. Executive Engineer, PWD, Silchar Building Sub-Division-I, Silchar for information with reference to his letter No. Misc/13/15 dt.08.05.2020.

Executive Engineer P.W.D.
Silchar Building Division,
Silchar